

HOMER AIRPORT

Contents:

- A Pavement Strength Form showing project history, latest Pavement Condition Index (PCI) data, pavement strength ratings (where available) and other useful information
- A Pavement Condition Survey – PCI Sample Unit Layout Plan
- PCI maps showing as-measured and predicted pavement conditions
- Age map showing pavement age as of January 2003
- A Branch PCI Condition Report
- A Section PCI Condition Report

Airport Information:

- Location: Southwest part of the Kenai Peninsula on the north side of Kachemak Bay.
- District: Peninsula District of the Central Region
- Airport Manager: Mike Morawitz
- District Maintenance Manager: Carl High
- Pavement Surface: Asphalt Concrete
- Last Pavement Construction: 2001
- Pavement layout: Runway 03-21, 4 aprons and 5 Taxiways
- Design Aircraft: C-130
- 2001 Enplanements: 32,936
- Airport Class: Primary
- Last pavement condition survey: 2002
- Next planned pavement condition survey: 2005
- 2002 reported pavement maintenance and/or changed conditions: None reported.
- Recommendations: See PCI maps